

Vehicle Condition Report

Vehicle VIN: 124677L147990



Vehicle Information

Year : 1967 Mileage : 46
 Brand : Chevrolet Exterior Color : Blue
 Model : Camaro Trim Color : Other
 Series : Trim Type : Vinyl
 Body Type : Convertible
 Drive Type : Rear Wheel Drive
 Engine : 5.3L, 8 Cylinder Engine, Gasoline Fuel
 Transmission : 3-Speed Automatic Transmission

Inspection Details

Inspection Date : 22 Sep 2014 1:02 PM
 Inspection ID : 50439
 Inspector : 4948

Grade : A

Inspection Notes : Unable to test drive vehicle as it's in the middle of showroom. Vehicle started right up and sounded good. Checked lights and horn. Reverse lights inop, 1 of the 2 horn units is inop thus single tone horn. Unable to lower convertible top at owner request. States that he didn't want to crease the newer vinyl top on vehicle... Unverifiable Miles Due to 5 Digit Odometer". Present odometer states 00046.... Please see photo of vehicle data sheet attached herein...

This 1967 Chevrolet Camaro is in pristine condition, inside and out. The restoration process it went through was front to back, left to right. Not being able to test drive the car, I will say the engine (327 C.I), sounded very nice, smooth and not out of time. The undercarriage found no fluid leaks as shown in the attached photos and very clean. This car is a classic winner all around....

Vehicle Accessories

Mechanical

- Battery

Wheels

- Chrome Wheels
- Power Brakes

Miscellaneous

- Rear Spoiler
- Soft Top

Tire Information

	Manufacturer	Size	Depth		Manufacturer	Size	Depth
Left Front :	BF Goodrich	225/70-14	11/32	Right Front :	BF Goodrich	225/70-14	10/32
Left Rear :	BF Goodrich	225/70-14	10/32	Right Rear :	BF Goodrich	225/70-14	11/32
Spare :	Firestone	125/70-15	5/32	*Tire Depth of 5/32 or greater is considered normal			

Vehicle Condition

Wear and Tear

Area	Type	Size
1 Other / See Notation BACKUP / REVERSE LIGHTS INOP	Inoperable	Minor
2 Other / See Notation ONE OF THE TWO HORN UNITS DOESNT SOUND, SINGLE TONE ONLY	Other / See Notation	Minor

Vehicle Inspection Points

Legend: ● Item inspected and is ok ● Item inspected and contains an issue ○ Item is not present or could not be inspected

Engine Compartment

Emission Sticker	●	Check Engine Compartment for Fluid Leaks	●
Notes: Missing			
Hood Struts Operation	●	Battery Is Secure	●
Underhood Insulation	●	Battery Condition	●
Hood Latch Operation	●	Check Transmission For Leaks	●

Engine Compartment-Parts and Fluid Levels

Windshield Washer Fluid Level	●	Check Power Steering Fluid Level	●
Inspect Hoses	●	Inspect Coolant Levels	●
Check For Engine Oil Sludge	●	Inspector Radiator Hose	●
Check Oil Level	●	Check Transmission Fluid	●
Inspect Belts	●	Check Master Cylinder For Brake Fluid	●

Exterior-Body Panels

Doors operate properly	●	Inspect Body Panels For Damage	●
Tailgate Operation	●	Inspect Roof for Damage	●
Inspect Undercarriage For Damage	●	Frame / Unibody	●
Inspect Truck Bed Condition	●	Check For Rust/ Corrosion	●
Inspect Paint Condition	●	Emblem/ Badge	●
Inspect Windshield and Other Glass for Damage	●	Inspect Quarter Panels for Damage	●
Inspect Fenders for Damage	●	Door And Side Moldings	●
Trunk Lid Closes Flush With Quarter Panel	●	Inspect Bumpers and Molding For Damage	●

Exterior-Electronic

Side Markers	●	Side Marker Lights	●
Headlights - Low/ High Beam	●	Tail Lights	●
License Plate Lights And Brackets	●	Reverse Lights	●
Notes: Inoperable / Broken			
Fog Lights	○	Brake Lights	●
High Center Third Brake Light	○		

Exterior-Hardware

Vehicle Identification Number On Door Jam	●	Vehicle Identification Number On Dashboard	○
Trunk Latch Functions	●	Convertible Top Operational	●
Notes: See Inspection Notes Section			
Front Wiper Blades	●	Side Mirrors	●
Remote Gas Cover Latch Operation	○	Gas Cap Condition	●
Door Handles Operational	●	Door Locks And Child Latches Function	●
Rear Window Windshield Wiper Arm	○	Antenna Mast Up/ Down	○

Rear Wiper Blades If Applicable	<input type="radio"/>	Side Mirror Extends	<input type="radio"/>
Chrome Parts	<input checked="" type="radio"/>	Roof Rack	<input type="radio"/>
Interior-Convenience and Power Controls			
Remote Key Fob Functions	<input type="radio"/>	Power Seats	<input type="radio"/>
Alarm	<input type="radio"/>	Power Sunroof	<input type="radio"/>
Rear Window Sunshade	<input type="radio"/>	Window Switches	<input type="radio"/>
Window Operation	<input checked="" type="radio"/>	Power Mirrors	<input type="radio"/>
Manual Door Locks	<input checked="" type="radio"/>	Manual Windows	<input checked="" type="radio"/>
Power Door Locks	<input type="radio"/>	Power Windows	<input type="radio"/>
Interior-Heating and A/C			
Cooled Seat Operation	<input type="radio"/>	Rear Defogger Grid Lines	<input type="radio"/>
Automatic Climate Control	<input type="radio"/>	Recirculating Air Mode	<input checked="" type="radio"/>
Heated Seat Operation	<input checked="" type="radio"/>	Vent Blower Speed	<input checked="" type="radio"/>
Air Conditioner Blows Cold Air	<input type="radio"/>	Heater Blows Warm Air	<input checked="" type="radio"/>
Fresh Air Mode	<input checked="" type="radio"/>		
Interior-Instruments / Controls			
Emergency Road Hazard Lights	<input checked="" type="radio"/>	Rear Window Wiper Controls	<input type="radio"/>
Gearshift Operation	<input type="radio"/>	Horn Functions	<input type="radio"/>
Notes: See Inspection Notes Section			
Check Engine Light	<input checked="" type="radio"/>	Sunvisor Vanity Mirrors	<input checked="" type="radio"/>
Airbag Warning Light	<input type="radio"/>	Dome Light	<input checked="" type="radio"/>
Odometer Operation	<input type="radio"/>	Parking Brake	<input checked="" type="radio"/>
Notes: See Inspection Notes Section			
Rear View Mirror/ Compass Function	<input checked="" type="radio"/>	Sunvisor Lights Function	<input checked="" type="radio"/>
Tilt Steering Column Functions	<input type="radio"/>	Warning Lights, Other	<input checked="" type="radio"/>
Knobs, Buttons and Other Controls	<input checked="" type="radio"/>	Dashboard Illumination	<input checked="" type="radio"/>
Defogger Indicator Light	<input checked="" type="radio"/>	Dashboard Condition	<input checked="" type="radio"/>
Cupholder Extends	<input type="radio"/>	Clock Functions	<input type="radio"/>
Cigarette Ligher Operational	<input type="radio"/>	Battery Gauge / Warning Light	<input checked="" type="radio"/>
Hood Release	<input checked="" type="radio"/>	Trunk Release	<input type="radio"/>
ABS Warning Light	<input type="radio"/>	Windshield Wiper Controls	<input checked="" type="radio"/>
Interior-Radio / Entertainment			
Rear Entertainment System and Controls	<input type="radio"/>	Rear Back-up Camera	<input type="radio"/>
Check Radio Controls	<input checked="" type="radio"/>	Speakers	<input checked="" type="radio"/>
Navigation System Operation	<input type="radio"/>	CD/DVD	<input type="radio"/>
Interior-Seating and Other Interior			

Vehicle Condition Report

Vehicle VIN: 124677L147990

Cargo Area Carpet	<input checked="" type="radio"/>	Airbag - Passenger	<input type="radio"/>
Seating Surfaces - Rear	<input checked="" type="radio"/>	Carpet - Front	<input checked="" type="radio"/>
Headliner Condition	<input type="radio"/>	Smoker Residue Or Odors	<input checked="" type="radio"/>
Tire Jack and Tools	<input checked="" type="radio"/>	Owner's Manual	<input type="radio"/>
Seatbelts - Front	<input checked="" type="radio"/>	Seating Surfaces - Front	<input checked="" type="radio"/>
Seat Position Adjusters	<input checked="" type="radio"/>	Spare Tire	<input checked="" type="radio"/>
Trunk Light Operational	<input type="radio"/>	Weather Stripping Condition	<input checked="" type="radio"/>
First Aid Kit If Applicable	<input type="radio"/>	Glove Box	<input checked="" type="radio"/>
Liftgate Struts	<input type="radio"/>	Toolkit Complete	<input type="radio"/>
Seatbelts - Rear	<input checked="" type="radio"/>	Windscreen Functionality, Convertible Top	<input style="background-color: yellow;" type="radio"/>
Notes: See Inspection Notes Section			
Door Sill Plates	<input checked="" type="radio"/>	Interior Trim	<input checked="" type="radio"/>
Tailgate Closing Assist	<input type="radio"/>	Armrest Condition	<input checked="" type="radio"/>
Headrests Function Properly	<input type="radio"/>	Airbag - Driver	<input type="radio"/>
Carpet - Rear	<input checked="" type="radio"/>		
Test Drive			
Cruise Control Operates	<input type="radio"/>	Steering Wheel Is Centered	<input type="radio"/>
Steering Wheel Operation	<input type="radio"/>	Cold/ Hot Starting	<input type="radio"/>
Engine Idling Normal	<input type="radio"/>	Engine Operating Temperature	<input type="radio"/>
Gears Range Operate Smoothly	<input type="radio"/>	Inspect For Brake Pulsation	<input type="radio"/>
Inspect For Excessive Smoke	<input type="radio"/>	Transmission/ Clutch Operation	<input type="radio"/>
Idle Smoothness	<input type="radio"/>	Speedometer Functions	<input type="radio"/>
Acceleration	<input type="radio"/>	Check For Squeaks	<input type="radio"/>
Check For Rattles	<input type="radio"/>	Check For Vibration	<input type="radio"/>
Excessive Wind Noise	<input type="radio"/>	Engine Noise	<input type="radio"/>
Suspension and Handling	<input type="radio"/>	Vehicle Tracks Straight	<input type="radio"/>
Starter Functionality	<input type="radio"/>	Check For Brake Noise	<input type="radio"/>
Inspect Backup Lights	<input type="radio"/>	Check For Unusual Tire Noise	<input type="radio"/>
Tires and Wheels			
Tire Condition and Tread Depth	<input checked="" type="radio"/>	Wheel Condition	<input checked="" type="radio"/>

Date : _____ 22 Sep 2014 _____	Signature : _____
--------------------------------	-------------------


V.4.1

Vehicle Pictures

Picture Description : **Roof**




Picture Description : **Int Cargo**



Picture Description : **Tire**



Picture Description : **Interior**



Picture Description : **Front Corner**



Picture Description : **Roof**



Vehicle Condition Report

Vehicle VIN: 124677L147990

Picture Description : **Tire**



Picture Description : **Engine**



Picture Description : **Rear**



Picture Description : **Int Cargo**



Picture Description : **Int Cargo**



Picture Description : **Engine**



Picture Description : **Front**



Picture Description : **Odometer**



Picture Description : **Key/CD/Manual**




Picture Description : **Rear**



Picture Description : **Rear Corner**



Picture Description : **Engine**



Vehicle Condition Report

Vehicle VIN: 124677L147990

Picture Description : **Interior**



Picture Description : **Tire**



Picture Description : **Vin**



Picture Description : **Int Cargo**



Picture Description : **Int Cargo**



Picture Description : **Engine**




Picture Description : **Right Side**




Picture Description : **Tire**



Picture Description : **Int Cargo**



Picture Description : **Interior**



Picture Description : **Engine**



Picture Description : **Interior**



Vehicle Condition Report

Vehicle VIN: 124677L147990

Picture Description : **Int Cargo**



Picture Description : **Interior**




Picture Description : **Interior**



Picture Description : **Interior**



Picture Description : **Int Cargo**



Picture Description : **Front**



Picture Description : **Interior**



Picture Description : **Interior**



Damage Pictures

Picture Description : **No Picture**

